



LOOKING NORTH AT EXISTING BRIDGE.
 DOTTED LINES INDICATE CANTILEVERS WHICH WERE INVESTIGATED AS A
 PROBABLE MEANS OF REINFORCING PRESENT BRIDGE.

REPORT ON LINDA VISTA BRIDGE SITE
 MAY 1923
 Lloyd A Walling